REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Re-Inspection | | Date: | 12/6/2021 | Time: | 9:10 AM |
|---------------------|--------------------|---------------|------------------|--------------|-----------------------|---------|
| Name of School Co | orporation: CAN | NELTON CITY S | SCHOOLS | | Corp ID: | 626340 |
| Address of School | Corporation: | 109 S 3rd St | | | | |
| City: | Cannelton | Zip: | 47520 | | County Number: | 62 |
| VIN: | 4UZABRDTXGC | GT3394 | License Number: | 23668 | Bus Number: | 5 |
| Make of Body: | Freightliner Year: | 2015 | Make of Chassis: | Freightliner | Year: | 2016 |
| Bus Type: | A1 | | Mileage: | Unknown | | |
| Inspection Status: | А | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.