REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	**Date:**	12/16/2021	**Time:**	8:54 AM
Name of School Corporation:	LEARNING LAND DAY CARE			**Corp ID:**	55002Z
Address of School Corporation:	960 S. Marion St				
City:	MARTINSVILLE	**Zip:**	46151	**County Number:**	55
VIN:	1GDHG31R6Y1229751	**License Number:**	B831L	**Bus Number:**	1
Make of Body:	Girardin Minibus, Inc. **Year:** 2000	**Make of Chassis:**	GMC	**Year:**	2000
Bus Type:		**Mileage:**	68934		
Inspection Status:	R	**Inspected By:**	Mark Raper	**PE:**	6473

Violations - Rejected

Inspection Code	Description
62-1-2	One (1) taillight or one (1) brake light does not function
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description