

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Registration	Date:	1/6/2022	Time:	10:49 AM
Name of School Corporation:	LOST RIVER CAREER CO-OP			Corp ID:	596150
Address of School Corporation:	610 Elm St Ste 1				
City:	Paoli	Zip:	57454	County Number:	59
VIN:	1G3HG31F521125340	License Number:	NBLRC1	Bus Number:	1
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	Chevrolet
Bus Type:	A1	Mileage:	Unknown		
Inspection Status:	O	Inspected By:	Philip Lubbers	PE:	7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
43-1-9	Any unauthorized lettering or markings are present on the body.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
8-2-1	There is no brake certification, or the certification has expired or is not signed
26-2-1	The fire extinguisher is missing
50-2-1	There is no seat belt cutter in the vehicle

### Bus Type Description

**Type A School Bus** - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.