

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/4/2022	Time:	9:19 AM		
Name of School Corporation:	FRANKTON-LAPEL COMM. SCHLS.			Corp ID:	485245		
Address of School Corporation:	7916 W 300 N						
City:	Anderson	Zip:	46011	County Number:	48		
VIN:	4DRBUC8PXMB407782		License Number:	23637	Bus Number:	55	
Make of Body:	IC Corporation	Year:	2019	Make of Chassis:	IC Corporation	Year:	2021
Bus Type:	C			Mileage:	24084		
Inspection Status:	O	Inspected By:	Jeremy Mason	PE:	8139		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
34-1-1	Any headlight is inoperative
11-1-1	The front bumper does not extend to the edge of the fenders
64-1-4	Any front turn signal does not function properly
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
59-1-15	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
25-2-2	Reflective glass is cracked, broken, or missing
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.