

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/13/2022	Time:	9:42 AM
Name of School Corporation:	MICHIGAN CITY AREA SCHOOLS	Corp ID:	464925		
Address of School Corporation:	408 S CARROLL AVE				
City:	Michigan City	Zip:	46360	County Number:	46
VIN:	1BAKJCBA9NF381035	License Number:	24749	Bus Number:	2102
Make of Body:	Blue Bird Corporation	Year:	2020	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	9064		
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-7	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
23-1-12	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.