## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:1/25/2022Time:9:45 AMName of School Corporation:SCOTT COUNTY SCHOOL DISTRICT 1Corp ID:727230

Address of School Corporation: US 31 S

City:AustinZip:47102County Number:72VIN:4DRBUSKP9EB352620License Number:NEW8XBus Number:8Make of Body:IC Corporation Year:2014Make of Chassis:IC Corporation Year:2014

Bus Type: C Mileage: 52270

Inspection Status: R Inspected By: Troy Boyd PE: 5171

## Violations - Rejected

Inspection Code	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.