

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/25/2022	Time:	1:42 PM
Name of School Corporation:	TRI-CENTRAL SCHOOLS	Corp ID:	807935		
Address of School Corporation:	2115 W 500 N				
City:	Sharpsville	Zip:	46068	County Number:	80
VIN:	1BAKFCPH68F250477	License Number:	B709Q	Bus Number:	2
Make of Body:	Blue Bird Corporation	Year:	2007	Make of Chassis:	Blue Bird Corporation
Bus Type:	C	Mileage:	137623		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
51-1-4	See Notes: Any defect inspector deems a violation not listed
57-1-8	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.