REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	1/25/2022	**Time:**	1:42 PM
Name of School Corporation:	TRI-CENTRAL SCHOOLS			**Corp ID:**	807935
Address of School Corporation:	2115 W 500 N				
City:	Sharpsville	**Zip:**	46068	**County Number:**	80
VIN:	1BAKFCPH68F250477	**License Number:**	B709Q	**Bus Number:**	2
Make of Body:	Blue Bird Corporation **Year:** 2007	**Make of Chassis:**	Blue Bird Corporation	**Year:**	2008
Bus Type:	C	**Mileage:**	137623		
Inspection Status:	O	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
51-1-4	See Notes: Any defect inspector deems a violation not listed
57-1-8	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code	Description
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.