## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Da	ate:	1/26/2022	Time:	9:19 AM
Name of School Address of Scho		SOUTHEAST DUBOIS CO. SCH. CORP 432 E 15th St				192100	
City:	Ferdinand	Zip:	47	7532		County Number:	19
VIN:	1BAAHCPA01F202	2164		cense umber:	B965B	Bus Number:	7
Make of Body:	Blue Bird Corporation	<b>Year:</b> 2001		ake of nassis:	Blue Bird Corporation	Year:	2001
Bus Type:	D		Mi	ileage:	128701		
Inspection Status:	R	Inspe By:	ected Ph	nilip Lubbers		PE:	7703

## **Violations - Rejected**

Inspection Code	<u>Description</u>
73-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
65-1-1	Any lens is cracked, broken or discolored
24-1-3	The bus is not painted National School Bus Yellow

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.