REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 1/28/2022 **Time:** 10:03 AM **Name of School Corporation:** MOORESVILLE CONS. SCHOOL CORP. **Corp ID:** 555930

Address of School Corporation: 173 Indianapolis Rd

City:MooresvilleZip:46158County Number: 55VIN:1FDEE3FL8CDA32519License Number: 34713Bus Number: 011Make of Body:Ford Year: 2012Make of Chassis: Ford Year: 2012

Bus Type: Mileage: 72757

Inspection Status: O Inspected By: Mark Raper PE: 6473

Violations - Rejected

Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)

Bus Type Description