REPORT OF SCHOOL BUS INSPECTION

Type of Annual 1/31/2022 **Time**: 9:54 AM Date: Inspection: Name of School Corporation: SOUTHEAST DUBOIS CO. SCH. CORP. 192100 Corp ID: **Address of School Corporation:** 432 E 15th St County City: Ferdinand Zip: 47532 19 Number: License VIN: B830H 1GBL7T1C51J509035 **Bus Number:** 1 Number: Blue Bird Make of Chevrolet Year: Make of Body: Year: 2001 2001 Corporation Chassis: **Bus Type:** С Mileage: 200113 Inspected PE: 7703 **Inspection Status:** R Philip Lubbers By:

Violations - Rejected

Inspection Code	<u>Description</u>
65-1-2	The area around any warning light is not painted black
24-1-7	See Notes: Any defect inspector deems a violation not listed
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.