

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 2/8/2022 Time: 9:03 AM  
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP. Corp ID: 596155  
Address of School Corporation: 501 S Elm St  
City: Paoli Zip: 47454 County Number: 59  
VIN: 4UZABRDD78CZ10900 License Number: B207Q Bus Number: 11  
Make of Body: Freightliner Year: 2007 Make of Chassis: Freightliner Year: 2008  
Bus Type: C Mileage: 158759  
Inspection Status: R Inspected By: Philip Lubbers PE: 7703

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                                                                  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|
| 23-1-5                 | Any hanger, clamp or bracket is missing, loose or broken                                                                                            |
| 23-1-3                 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |
| 43-1-8                 | Any required lettering is missing or faded.                                                                                                         |
| 65-1-1                 | Any lens is cracked, broken or discolored                                                                                                           |

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.