

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	2/8/2022	Time:	10:59 AM		
Name of School Corporation:	SOUTH NEWTON SCHOOL CORP.			Corp ID:	565995		
Address of School Corporation:	13232 S 50 E						
City:	Kentland	Zip:	47951	County Number:	56		
VIN:	4DRBUC8P0GB103266		License Number:	9627	Bus Number:	1	
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation	Year:	2016
Bus Type:	C			Mileage:	62631		
Inspection Status:	O	Inspected By:	Tim Grayson	PE:	7558		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
34-1-1	Any headlight is inoperative
67-1-2	Rims are bent or loose
11-1-1	The front bumper does not extend to the edge of the fenders
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
63-1-1	Any tire has low air pressure

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
53-2-5	"U" bolts are loose, broken, or missing
11-2-2	A bumper does not meet manufactures specifications
63-2-3	Any tire is flat

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.