

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Re-Inspection	Date: 2/10/2022	Time: 9:14 AM	
Name of School Corporation: NORTH LAWRENCE COMM. SCHOOLS	Corp ID: 475075		
Address of School Corporation: 595 Stars Blvd			
City: Bedford	Zip: 47421	County Number: 47	
VIN: 4DRBUAA28B561180	License Number: nlcsa-13	Bus Number: A58	
Make of Body: IC Corporation	Year: 2007	Make of Chassis: IC Corporation	Year: 2008
Bus Type: C	Mileage: 159646		
Inspection Status: R	Inspected By: Mike Adams	PE: 7407	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.