## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:Re-InspectionDate:2/10/2022Time:9:14 AMName of School Corporation:NORTH LAWRENCE COMM. SCHOOLSCorp ID:475075

Name of School Corporation: NORTH LAWRENCE COMM. SCHOOL Address of School Corporation: 595 Stars Blvd

City: Bedford Zip: 47421 County Number: 47

VIN: 4DRBUAA28B561180 License Number: nlcsa-13 Bus Number: A58

Make of Body: IC Corporation Year: 2007 Make of Chassis: IC Corporation Year: 2008

Bus Type: C Mileage: 159646

Inspection Status: R Inspected By: Mike Adams PE: 7407

## **Violations - Rejected**

Inspection Code Description

Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.