REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		Date:	2/11/2022	Time:	10:39 AM
Name of Schoo Address of Sch	I Corporation: MA ool Corporation:	ACONAQUAH S 7932 S Stra	SCHOOL CORPO wtown Pike	DRATION	Corp ID:	525615
City:	Bunker Hill	Zip:	46914		County Number:	52
VIN:	4UZABRDT7GCHG5703	3	License Number:	10579	Bus Number:	34
Make of Body:	Thomas Built Buses, Ye Inc.	ar: 2015	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2016
Bus Type:	С		Mileage:	145384		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

<u>Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
62-1-10	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.