

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Semi-Annual	<b>Date:</b> 2/15/2022	<b>Time:</b> 8:53 AM	
<b>Name of School Corporation:</b> CANTERBURY SCHOOL (02)	<b>Corp ID:</b> 02A285		
<b>Address of School Corporation:</b> 5601 Covington Road			
<b>City:</b> Fort Wayne	<b>Zip:</b> 46804	<b>County Number:</b> 2	
<b>VIN:</b> 4DRBUAFP86B230871	<b>License Number:</b> B593D	<b>Bus Number:</b> 30	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2006	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2006
<b>Bus Type:</b> C	<b>Mileage:</b> 152028		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Eric Egbert	<b>PE:</b> 7006	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
22-1-1	A dripping oil or fluid leak
68-1-4	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-1	Any crossmember is cracked or broken
32-2-1	There is fuel leaking from any point on in the fuel system

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**