

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                 |                         |                |
|---------------------------------------|--------------------------------|------------------------|-----------------|-------------------------|----------------|
| <b>Type of Inspection:</b>            | Annual                         | <b>Date:</b>           | 2/22/2022       | <b>Time:</b>            | 9:27 AM        |
| <b>Name of School Corporation:</b>    | HERITAGE HALL CHRISTIAN SCHOOL |                        |                 | <b>Corp ID:</b>         | 18-PS-HHC      |
| <b>Address of School Corporation:</b> | 6401 West River Road           |                        |                 |                         |                |
| <b>City:</b>                          | Muncie                         | <b>Zip:</b>            | 47304           | <b>County Number:</b>   | 18             |
| <b>VIN:</b>                           | 1HVBBPLP2NH447968              | <b>License Number:</b> | B246AD          | <b>Bus Number:</b>      | 5              |
| <b>Make of Body:</b>                  | IC Corporation                 | <b>Year:</b>           | 1992            | <b>Make of Chassis:</b> | IC Corporation |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | 243995          | <b>Year:</b>            | 1992           |
| <b>Inspection Status:</b>             | R                              | <b>Inspected By:</b>   | Jamie Hotchkiss | <b>PE:</b>              | 6458           |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                       |
|------------------------|--|
| 35-1-1                 | A heater motor is not operating properly |

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**