

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	3/1/2022	Time:	12:29 PM		
Name of School Corporation:	SEYMOUR COMMUNITY SCHOOLS			Corp ID:	363675		
Address of School Corporation:	1638 S Walnut St						
City:	Seymour	Zip:	47274	County Number:	36		
VIN:	4DRBUAAN9BB335077		License Number:	74352	Bus Number:	26	
Make of Body:	IC Corporation	Year:	2010	Make of Chassis:	IC Corporation	Year:	2011
Bus Type:	C			Mileage:	150616		
Inspection Status:	O	Inspected By:	Mike Adams	PE:	7407		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-1	The latch does not secure the hood tightly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.