

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/7/2022	<b>Time:</b> 10:35 AM
<b>Name of School Corporation:</b> HOLY TRINITY CATHOLIC SCHOOL	<b>Corp ID:</b> 19A865	
<b>Address of School Corporation:</b> 990 Church Ave		
<b>City:</b> Jasper	<b>Zip:</b> 47546	<b>County Number:</b> 19
<b>VIN:</b> 4UZ3CJAA0YCF26302	<b>License Number:</b> B110L	<b>Bus Number:</b> 2
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 1999	<b>Make of Chassis:</b> Freightliner
<b>Year:</b> 2000	<b>Mileage:</b> 161925	
<b>Bus Type:</b> C		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Philip Lubbers	<b>PE:</b> 7703

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
46-1-1	Any seat is loose from the floor or seat rail
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
65-1-3	Black paint is faded

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.