## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection:	Annual		Date:	3/10/2022	Time:	9:59 AM
Name of School Co	COMM. SCHOOL	3	Corp ID:	475075		
Address of School	Corporation:	595 Stars Blvd				
City:	Bedford	Zip:	47421		<b>County Number:</b>	47
VIN:	1GB3GSBG6L1	259187	License Number:	25064	Bus Number:	V44
Make of Body:	Chevrolet Year:	2020	Make of Chassis:	Chevrolet	Year:	2020
Bus Type:			Mileage:	4772		
Inspection Status:	А	Inspected By:	Mike Adams		PE:	7407

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

**Bus Type Description**