## REPORT OF SCHOOL BUS INSPECTION

Type of 11:20 Time: Annual Date: 3/28/2022 Inspection: AM Name of School Corporation: SCHOOL CITY OF EAST CHICAGO Corp ID: 454670 1401 E 144th St **Address of School Corporation:** County City: East Chicago Zip: 46312 45 Number: License VIN: 1BAKGCBH5KF356723 356723 **Bus Number:** 25 Number: Make of Blue Bird Blue Bird Year: 2018 Make of Body: Year: 2019 Corporation Chassis: Corporation **Bus Type:** С Mileage: 26918 Inspection Inspected R PE: Tim Grayson 7558 Status: By:

## **Violations - Rejected**

## <u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

13-1-1 Any clearance light is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.