

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |              |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|--------------|
| <b>Type of Inspection:</b>            | Post-Crash Inspection          | <b>Date:</b>           | 3/28/2022      | <b>Time:</b>            | 2:06 PM      |
| <b>Name of School Corporation:</b>    | PERRY CENTRAL COMM. SCH. CORP. | <b>Corp ID:</b>        | 626325         |                         |              |
| <b>Address of School Corporation:</b> | 18677 Old State Rd 37          |                        |                |                         |              |
| <b>City:</b>                          | Leopold                        | <b>Zip:</b>            | 47551          | <b>County Number:</b>   | 62           |
| <b>VIN:</b>                           | 4UZABRDT5FCGN2593              | <b>License Number:</b> | 8782           | <b>Bus Number:</b>      | 12           |
| <b>Make of Body:</b>                  | Thomas Built Buses, Inc.       | <b>Year:</b>           | 2014           | <b>Make of Chassis:</b> | Freightliner |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | Unknown        |                         |              |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Philip Lubbers | <b>PE:</b>              | 7703         |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

|        |   |
|--------|---|
| 24-2-1 | There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)). |
| 24-2-2 | Any body surface protrudes beyond the normal limits of the body structure   |
| 25-2-2 | Reflective glass is cracked, broken, or missing   |

#### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.