

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                                |                        |                |                         |         |
|---------------------------------------|--------------------------------|------------------------|----------------|-------------------------|---------|
| <b>Type of Inspection:</b>            | Re-Inspection                  | <b>Date:</b>           | 3/30/2022      | <b>Time:</b>            | 9:07 AM |
| <b>Name of School Corporation:</b>    | SPRINGS VALLEY COMM. SCH. CORP | <b>Corp ID:</b>        | 596160         |                         |         |
| <b>Address of School Corporation:</b> | 498 S Larry Bird Blvd          |                        |                |                         |         |
| <b>City:</b>                          | French Lick                    | <b>Zip:</b>            | 47432          | <b>County Number:</b>   | 59      |
| <b>VIN:</b>                           | 1GDL7T1C22J509907              | <b>License Number:</b> | 21603          | <b>Bus Number:</b>      | 8       |
| <b>Make of Body:</b>                  | Blue Bird Corporation          | <b>Year:</b>           | 2002           | <b>Make of Chassis:</b> | GMC     |
| <b>Year:</b>                          | 2003                           |                        |                |                         |         |
| <b>Bus Type:</b>                      | C                              | <b>Mileage:</b>        | 159798         | <b>PE:</b>              | 7703    |
| <b>Inspection Status:</b>             | O                              | <b>Inspected By:</b>   | Philip Lubbers |                         |         |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                        |
|------------------------|-----------------------------------------------------------------------------------------------------------|
| 30-1-2                 | There are weak areas due to deterioration                                                                 |
| 57-1-1                 | Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.) |
| 43-1-8                 | Any required lettering is missing or faded.                                                               |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**