

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 3/30/2022	<b>Time:</b> 10:00 AM
<b>Name of School Corporation:</b> PRIMROSE SCHOOL @ BRIDGEWATER		<b>Corp ID:</b> 290007
<b>Address of School Corporation:</b> 14711 N. Gray Rd.		
<b>City:</b> Westfield	<b>Zip:</b> 46062	<b>County Number:</b> 29
<b>VIN:</b> 1GB0G2BA3D1180155	<b>License Number:</b> B741P	<b>Bus Number:</b> 1A
<b>Make of Body:</b> Chevrolet	<b>Year:</b> 2013	<b>Make of Chassis:</b> Girardin Minibus, Inc.
<b>Bus Type:</b> A1	<b>Mileage:</b> 31053	<b>Year:</b> 2013
<b>Inspection Status:</b> O	<b>Inspected By:</b> Jeff Stone	<b>PE:</b> 8184

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
22-1-1	A dripping oil or fluid leak

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.