

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/1/2022	Time:	10:55 AM		
Name of School Corporation:	BENTON COMMUNITY SCHOOL CORP.			Corp ID:	40395		
Address of School Corporation:	PO Box 512						
City:	Fowler	Zip:	47944	County Number:	4		
VIN:	4DRBUC8N6FB709555		License Number:	9003	Bus Number:	1441	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2015
Bus Type:	C			Mileage:	66639		
Inspection Status:	R	Inspected By:	Nate King	PE:	7421		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.