# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | | **Date:** | 4/4/2022 | **Time:** | 8:33 AM |
| **Name of School Corporation:** | HANOVER COMM. SCHOOL CORP. | | | | **Corp ID:** | 454580 |
| **Address of School Corporation:** | | PO Box 645 | | | | |
| **City:** | Cedar Lake | **Zip:** | 46303 | | **County Number:** | 45 |
| **VIN:** | 1GB3G2BG1C1196659 | | **License Number:** | 14188 | **Bus Number:** | 44 |
| **Make of Body:** | Star Trans **Year:** | 2012 | **Make of Chassis:** | Chevrolet | **Year:** | 2012 |
| **Bus Type:** | | | **Mileage:** | 78743 | | |
| **Inspection Status:** | A | **Inspected By:** | Tim Grayson | | **PE:** | 7558 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type Description |
|---|