

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---------------------------------------|----------------------------|------------------------|-------------|-------------------------|-----------|--------------|------|
| Type of Inspection: | Annual | Date: | 4/4/2022 | Time: | 8:37 AM | | |
| Name of School Corporation: | HANOVER COMM. SCHOOL CORP. | | | Corp ID: | 454580 | | |
| Address of School Corporation: | PO Box 645 | | | | | | |
| City: | Cedar Lake | Zip: | 46303 | County Number: | 45 | | |
| VIN: | 1GB3G3BG5C1130136 | License Number: | 5061 | Bus Number: | 22 | | |
| Make of Body: | Collins Bus Corporation | Year: | 2012 | Make of Chassis: | Chevrolet | Year: | 2012 |
| Bus Type: | A2 | Mileage: | 120224 | | | | |
| Inspection Status: | A | Inspected By: | Tim Grayson | PE: | 7558 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**