

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	4/5/2022	Time:	1:03 PM		
Name of School Corporation:	UNION TOWNSHIP SCHOOL CORP			Corp ID:	646530		
Address of School Corporation:	599 W 300 N A						
City:	Valparaiso	Zip:	46385	County Number:	64		
VIN:	1BAKCCPAXAF274055		License Number:	75072	Bus Number:	16	
Make of Body:	Blue Bird Corporation	Year:	2009	Make of Chassis:	Blue Bird Corporation	Year:	2010
Bus Type:	C			Mileage:	130108		
Inspection Status:	O	Inspected By:	Nathan Sherer	PE:	7029		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
55-1-6	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.