## REPORT OF SCHOOL BUS INSPECTION

Type of 9:27 4/7/2022 **Time**: Post-Crash Inspection Date: Inspection: AM Name of School Corporation: SWITZERLAND COUNTY SCHOOL CORP 787775 Corp ID: **Address of School Corporation:** 1040 W Main St County City: Zip: 47043 78 Vevay Number: License VIN: 1HA6GUBG4HN006613 J877615 Bus Number: 68 Number: Make of Thomas Built Buses, Year: 2019 Chevrolet Year: Make of Body: 2018 Inc. Chassis: **Bus Type:** С Mileage: 74908 Inspected PE: **Inspection Status:** O Chris Clark 6665 By:

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

Inspection Code Description

There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.