

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 4/8/2022	<b>Time:</b> 1:44 PM	
<b>Name of School Corporation:</b> CITY BAPTIST SCHOOLS		<b>Corp ID:</b> 45B985	
<b>Address of School Corporation:</b> 4925 S Sohl Ave			
<b>City:</b> Hammond	<b>Zip:</b> 46327	<b>County Number:</b> 45	
<b>VIN:</b> 4DRBRAAP64B974684	<b>License Number:</b> B455M	<b>Bus Number:</b> 158	
<b>Make of Body:</b> IC Corporation	<b>Year:</b> 2004	<b>Make of Chassis:</b> IC Corporation	<b>Year:</b> 2004
<b>Bus Type:</b> C	<b>Mileage:</b> 190539		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Tim Grayson	<b>PE:</b> 7558	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
55-1-3	Power steering is inoperative
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
51-1-1	Any door seals are missing, damaged, or torn
52-1-1	There are any loose, broken, or missing mountings
52-1-4	Any shock absorber is broken or missing
57-1-2	Step-well area is weakened
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
53-2-5	"U" bolts are loose, broken, or missing
53-2-3	Coil springs, torque rods or torsion bars are broken or missing
53-2-1	Any broken main leaf in a leaf spring
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
24-2-2	Any body surface protrudes beyond the normal limits of the body structure
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
55-2-3	Any steering component jams or inhibits safe movement
63-2-3	Any tire is flat
51-2-1	The service door does not open or close properly
65-2-1	Warning lights fail to operate correctly
8-2-12	There is any defect, which the inspector feels would adversely affect the ability of the vehicle to stop safely

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**