

## REPORT OF SCHOOL BUS INSPECTION

|  |                                     |  |
|--|-------------------------------------|--|
| <b>Type of Inspection:</b> Annual                              | <b>Date:</b> 4/19/2022              | <b>Time:</b> 8:06 AM                   |
| <b>Name of School Corporation:</b> SOUTHWEST DUBOIS SCH. CORP. | <b>Corp ID:</b> 192110              |  |
| <b>Address of School Corporation:</b> 105 W Sunset Dr          |                                     |  |
| <b>City:</b> Huntingburg                                       | <b>Zip:</b> 47542                   | <b>County Number:</b> 19               |
| <b>VIN:</b> 4DRBUAAN5AB220748                                  | <b>License Number:</b> B790B        | <b>Bus Number:</b> 11                  |
| <b>Make of Body:</b> IC Corporation                            | <b>Year:</b> 2009                   | <b>Make of Chassis:</b> IC Corporation |
| <b>Year:</b> 2010  | <b>Mileage:</b> 108763              |  |
| <b>Bus Type:</b> C   |                                     | <b>PE:</b> 7703                        |
| <b>Inspection Status:</b> O                                    | <b>Inspected By:</b> Philip Lubbers |  |

### Violations - Rejected

#### Inspection Code Description

### Violations - Out of Service

#### Inspection Code

#### Description

|        |   |
|--------|---|
| 18-2-3 | Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber) |
|--------|---|

#### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**