## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			Date:	4/21/2022	Time:	1:19 PM
Name of School Address of School	Corporation:		IWEST DUI 05 W Suns	BOIS SCH. COR et Dr	RP.	Corp ID:	192110
City:	Huntingburg	Zi	ip:	47542		County Number:	19
VIN:	1T7YT4E2XB113124			License Number:	515	Bus Number:	8
Make of Body:	Thomas Built Buses, Inc.	Year: 20	010	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2011
Bus Type:	D			Mileage:	Unknown		
Inspection Status:	R	_	nspected By:	Philip Lubbers		PE:	7703

## Violations - Rejected

Inspection Code	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.