REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	4/19/2022	**Time:**	9:51 AM
Name of School Corporation:	BLUE RIVER VALLEY SCHOOLS					**Corp ID:**	333405
Address of School Corporation:	PO Box 217						
City:	Mount Summit	**Zip:**	47361			**County Number:**	33
VIN:	1UZABRCS88CY45720			**License Number:**	30828	**Bus Number:**	17
Make of Body:	Mid Bus, Inc.	**Year:**	2006	**Make of Chassis:**	Freightliner	**Year:**	2006
Bus Type:	C			**Mileage:**	62866		
Inspection Status:	O	**Inspected By:**	Jeremy Mason			**PE:**	8139

Violations - Rejected

Inspection Code	Description
57-1-1	Step covering is loose, buckled, or made of a material other than rubber (i.e. rugs, carpets, mats, etc.)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.