

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------------|------------------------|-----------------|-------------------------|--------------------------|
| Type of Inspection: | Annual | Date: | 4/22/2022 | Time: | 9:53 AM |
| Name of School Corporation: | RANDOLPH SOUTHERN SCHOOL CORP. | | | Corp ID: | 686805 |
| Address of School Corporation: | One Rebel Dr | | | | |
| City: | Lynn | Zip: | 47355 | County Number: | 68 |
| VIN: | 4UZABRFD2LCLH7940 | License Number: | 22636 | Bus Number: | 1 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2018 | Make of Chassis: | Thomas Built Buses, Inc. |
| Bus Type: | C | Mileage: | 34644 | Year: | 2019 |
| Inspection Status: | O | Inspected By: | Jamie Hotchkiss | PE: | 6458 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 8-1-3 | ABS warning light is illuminated |
| 22-1-2 | The engine has excessive oil or grime build-up, or if there is dirt or fluid standing on the engine (i.e. oil, coolant, etc.) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.