REPORT OF SCHOOL BUS INSPECTION

Type of 8:55 Annual Time: Date: 4/26/2022 Inspection: AM Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL Corp ID: 141375 **Address of School Corporation:** 5494 E SR 58 County City: Elnora Zip: 47529 14 Number: License VIN: B590C 1BAKFCKH56F233657 Bus Number: Number: Make of Blue Bird Blue Bird Make of Body: Year: 2005 Year: 2006 Corporation Chassis: Corporation **Bus Type:** С Mileage: 158422 Inspection Inspected R PE: 7703 Philip Lubbers Status: By:

Violations - Rejected

Inspection Code	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.