

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/26/2022	Time: 9:59 AM	
Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL	Corp ID: 141375		
Address of School Corporation: 5494 E SR 58			
City: Elnora	Zip: 47529	County Number: 14	
VIN: 4DRBUC8P4GB734618	License Number: 9535	Bus Number: ND7	
Make of Body: IC Corporation	Year: 2014	Make of Chassis: IC Corporation	Year: 2016
Bus Type: C	Mileage: 59055		
Inspection Status: R	Inspected By: Philip Lubbers	PE: 7703	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
17-1-1	Any dome light is inoperative
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.