## REPORT OF SCHOOL BUS INSPECTION

Type of 10:45 4/26/2022 Time: Annual Date: Inspection: AM Name of School Corporation: OAK HILL UNITED SCHOOL CORP. 525625 Corp ID: **Address of School Corporation:** PO Box 550 County City: Converse Zip: 46919 52 Number: License VIN: 4UZABRFC6KCJZ5474 1131 **Bus Number:** 14 Number: Make of Thomas Built Buses, Year: 2017 Freightliner Year: Make of Body: 2019 Inc. Chassis: **Bus Type:** С Mileage: 60229 Inspection Inspected R PE: 7018 Randy McPike Status: By:

**Violations - Rejected** 

<u>Inspection Code</u> <u>Description</u>

44-1-1 Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.