## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/27/2022 Time: 9:10 AM

Name of School Corporation: NORTH DAVIESS CO. COMM. SCHOOL

**Corp ID**: 141375

**Address of School Corporation:** 5494 E SR 58

City:ElnoraZip:47529County Number:14VIN:4DRBUAFP28B556801License Number:B399SBus Number:16Make of Body:IC Corporation Year:2008

Bus Type: C Mileage: 92487

Inspection Status: R Inspected By: Philip Lubbers PE: 7703

## Violations - Rejected

## <u>Inspection Code</u> <u>Description</u>

57-1-5 Step-well light is missing or inoperative

64-1-4 Any front turn signal does not function properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.