

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 4/27/2022	Time: 9:49 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP.	Corp ID: 525625	
Address of School Corporation: PO Box 550		
City: Converse	Zip: 46919	County Number: 52
VIN: 1BAKBCPA2JF337233	License Number: 5851	Bus Number: 26
Make of Body: Blue Bird Corporation	Year: 2016	Make of Chassis: Blue Bird Corporation
Bus Type: C	Mileage: 118596	Year: 2018
Inspection Status: R	Inspected By: Randy McPike	PE: 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
59-1-9	There is air leak at the stop arm air bladder that does not affect the air braking system

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.