

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/27/2022	Time:	10:19 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4UZABRFC8KCJZ5475	License Number:	1129	Bus Number:	20		
Make of Body:	Thomas Built Buses, Inc.	Year:	2017	Make of Chassis:	Freightliner	Year:	2019
Bus Type:	C	Mileage:	65022				
Inspection Status:	R	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.