

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	4/27/2022	Time:	10:46 AM
Name of School Corporation:	PRIMROSE SCHOOL @ WEST CLAY	Corp ID:	46032		
Address of School Corporation:	13096 Moultrie St.				
City:	Carmel	Zip:	46032	County Number:	29
VIN:	1GBHG31C381231865	License Number:	PRB3	Bus Number:	J2
Make of Body:	Collins Bus Corporation	Year:	2008	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	51415	Year:	2008
Inspection Status:	R	Inspected By:	Nick Cox	PE:	8795

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-2	See Notes: Any defect inspector deems a violation not listed
22-1-5	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

## Violations - Out of Service

### Inspection Code Description

### Bus Type Description

**Type A School Bus** - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.