REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			**Date:**	4/27/2022	**Time:**	10:46 AM
Name of School Corporation:		PRIMROSE SCHOOL @ WEST CLAY				**Corp ID:**	46032
Address of School Corporation:		13096 Moultrie St.					
City:	Carmel	**Zip:**	46032			**County Number:**	29
VIN:	1GBHG31C381231865			**License Number:**	PRB3	**Bus Number:**	J2
Make of Body:	Collins Bus Corporation	**Year:**	2008	**Make of Chassis:**	Chevrolet	**Year:**	2008
Bus Type:	A2			**Mileage:**	51415		
Inspection Status:	R	**Inspected By:**	Nick Cox			**PE:**	8795

Violations - Rejected

Inspection Code	Description
49-1-2	See Notes: Any defect inspector deems a violation not listed
22-1-5	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**