REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/27/2022 Time: 11:01 AM Name of School Corporation: PRIMROSE WEST CARMEL Corp ID: 1100382

Address of School Corporation: 3746 W. 96th st

City:CarmelZip:46032County Number:29VIN:1GB0G2BA0D1109849License Number:B787PBus Number:A2Make of Body:Chevrolet Year:2013Make of Chassis:Chevrolet Year:2013

Bus Type: A1 Mileage: 30450

Inspection Status: O Inspected By: Nick Cox PE: 8795

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

41-1-4 There is debris in the bus. (needs cleaned/includes dirt)

22-1-1 A dripping oil or fluid leak

24-1-7 See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code Description

Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.