

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 4/27/2022 Time: 11:01 AM  
Name of School Corporation: PRIMROSE WEST CARMEL Corp ID: 1100382  
Address of School Corporation: 3746 W. 96th st  
City: Carmel Zip: 46032 County Number: 29  
VIN: 1GB0G2BA0D1109849 License Number: B787P Bus Number: A2  
Make of Body: Chevrolet Year: 2013 Make of Chassis: Chevrolet Year: 2013  
Bus Type: A1 Mileage: 30450  
Inspection Status: O Inspected By: Nick Cox PE: 8795

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
22-1-1	A dripping oil or fluid leak
24-1-7	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.