REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/27/2022	**Time:**	11:01 AM
Name of School Corporation:	PRIMROSE WEST CARMEL			**Corp ID:**	1100382
Address of School Corporation:	3746 W. 96th st				
City:	Carmel	**Zip:**	46032	**County Number:**	29
VIN:	1GB0G2BA0D1109849	**License Number:**	B787P	**Bus Number:**	A2
Make of Body:	Chevrolet **Year:** 2013	**Make of Chassis:**	Chevrolet	**Year:**	2013
Bus Type:	A1	**Mileage:**	30450		
Inspection Status:	O	**Inspected By:**	Nick Cox	**PE:**	8795

Violations - Rejected

Inspection Code	Description
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
22-1-1	A dripping oil or fluid leak
24-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
63-2-1	Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**