REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 5/9/2022 **Time:** 12:21 PM

Name of School Corporation: PROVIDENCE CRISTO REY Corp ID:

Address of School Corporation: 2717 S EAST STREET

City:IndianapolisZip:46225County Number: 49VIN:1GBJG31U051240898License Number: B767PBus Number: 1Make of Body:Chevrolet Year: 2005Make of Chassis: AmTranYear: 2005

Bus Type: A1 Mileage: 84180

Inspection Status: O Inspected By: Joel Flores PE: 7415

Violations - Rejected

Inspection Code	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
34-1-1	Any headlight is inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.