

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 5/9/2022 Time: 12:21 PM
Name of School Corporation: PROVIDENCE CRISTO REY Corp ID:
Address of School Corporation: 2717 S EAST STREET
City: Indianapolis Zip: 46225 County Number: 49
VIN: 1GBJG31U051240898 License Number: B767P Bus Number: 1
Make of Body: Chevrolet Year: 2005 Make of Chassis: AmTran Year: 2005
Bus Type: A1 Mileage: 84180
Inspection Status: O Inspected By: Joel Flores PE: 7415

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-2	A lens is cracked, missing or wrong color
34-1-1	Any headlight is inoperative
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
11-2-2	A bumper does not meet manufactures specifications

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.