REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection			**Date:**	5/9/2022	**Time:**	11:19 AM
Name of School Corporation:		NETTLE CREEK SCHOOL CORP.				**Corp ID:**	898305
Address of School Corporation:		795 Baker Rd					
City:	Hagerstown	**Zip:**	47346			**County Number:**	89
VIN:	1T88T4E2181103086			**License Number:**	31422	**Bus Number:**	7
Make of Body:	Thomas Built Buses, Inc.	**Year:**	2007	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2008
Bus Type:	D			**Mileage:**	154008		
Inspection Status:	O	**Inspected By:**	Jeremy Mason			**PE:**	8139

Violations - Rejected

Inspection Code	Description
22-1-1	A dripping oil or fluid leak
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description
70-2-3	Any emergency window will not open
57-2-1	Any part of the step-well or support structure is rusted through

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.