REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Annual | | | Date: | 5/10/2022 | Time: | 8:58 AM |
|--------------------------------|-----------------------------|-------|--------------------------------|---------------------|--------------|-------------------|------------|
| Name of School Corporation: C | | CRA | CRAWFORD CO. COMM. SCHOOL CORP | | | Corp ID: | 131300 |
| Address of School Corporation: | | | 5808 E Administration Rd | | | | |
| City: | Marengo | | Zip: | 47140 | | County Number: | 13 |
| VIN: | 4UZABRDT8HCHP8465 | | License Number: | 23240 | Bus Number: | 6 | |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2015 | Make of Chassis: | Freightliner | Year: | 2017 |
| Bus Type: | A2 | | | Mileage: | 40218 | | |
| Inspection Status | :: R | | Inspected By: | Philip Lubbers | | PE: | 7703 |

Violations - Rejected

Inspection CodeDescription57-1-5Step-well light is missing or inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.

2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.